

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG. 7




FIG. 8




FIG.9




FIG.10




FIG.11



5/16
BUR920030078US1




FIG. 12



6/16
BUR920030078US1




FIG. 13




FIG. 14



8/16
BUR920030078US1




FIG. 15



9/16
BUR920030078US1

WELL MASK




FIG.16

MANDREL MASK




FIG17

164
N-WELL OR P-WELL




FIG.18




FIG. 19




FIG. 20




FIG. 21




FIG.22




FIG.23




FIG.24



12/16
BUR920030078US1




FIG.25




FIG.26




FIG.27



13/16
BUR920030078US1




FIG.28



14/16
BUR920030078US1





FIG. 29






FIG.31